



**RESUME WORK  
IN THE MATTER OF THE NATIONAL ENERGY BOARD ACT,  
FOLLOWING AN ORDER UNDER SECTION 51.1**


**26 November 2014, 1200 HRS**

On 26 November 2014, 1200 HRS, the undersigned National Energy Board Inspection Officer hereby  
Date/time

notifies Excavation Claude Guertin Inc. that the hazardous or detrimental situation  
Company Representative and company name

described in Order No. KAR-002-2014 has been remedied to the satisfaction of the Inspection Officer.  
Inspection Officer order

Therefore,  Suspended work may resume, and/or  
 the measures specified in the order have been satisfied.

Inspection Officer		#1554	
	Name	IO Designation #	Telephone
	26 November 2014		
	Date		
Centre 10 – 517, 10th Avenue SW Calgary AB T2R 0A8			